

Fig. 6-100 Lead Screw Bracket. Draw or sketch necessary views (Layout C–3).



Fig. 6-99 Automatic Stop Base. Draw or sketch necessary views (Layout C–3).



Fig. 6-102 Gripper Rod Center. Draw or sketch necessary views (Layout B–3).



Fig. 6-101 Lever Bracket. Draw or sketch necessary views (Layout C–3).