

Fig. 6-117 Boom Swing Bearing for a Power Crane.

Given: Front and bottom views.
Required: Front, top, and left-side views (Layout C–4).



Fig. 6-116 Horizontal Bracket for Broaching Machine.

Given: Front and top views.

Required: Take top as front view in new drawing; then add top and left-side views (Layout C–4).