



**Fig. 14-57 Machinist's Clamp.** Draw details and assembly. If assigned, use unidirectional two-place decimal dimensions.