



**Fig. 14-62 Tap Wrench.** (1) Draw details. (2) Draw assembly. If assigned, use unidirectional two-place decimals for all fractional dimensions.